



Drivers Pack 3.55

Driver package of IP devices for Axxon Intellect and Axxon Next software

December 28, 2018. Release notes

For information about the Drivers Pack, refer [here](#).

44 new IP devices are integrated

IP cameras:

- Axis M3025
- Axis Q1614
- Beward B2710RV-B1
- Beward B2710RVZ-B1
- Beward B89L2-5230Z40
- Dahua DH-IPC-HDBW8231E-Z5E
- Dahua DH-IPC-HDBW8231E-ZE
- Dahua DH-IPC-HDBW8232E-Z
- Dahua DH-IPC-HDBW8232E-ZE
- Dahua DH-IPC-HF8232F-E
- Dahua DH-IPC-HF8331F-E
- Dahua DH-IPC-HFW5231EP-Z12E
- Dahua DH-IPC-HFW8231E-Z5E
- Dahua DH-IPC-HFW8231E-ZE
- Dahua DH-IPC-HFW8331E-ZE
- GIT GIT-CNW23600/CHR
- Grundig GCI-F1505B
- Hanwha Techwin PND-9080R
- Hanwha Techwin PNV-9080R
- Hanwha Techwin SNB-5000A
- Hanwha Techwin SNB-5000A
- Hikvision DS-2CD2743G0-IZS
- LTV CNE-420 00
- LTV CNE-641 58
- LTV CNE-680 58
- LTV CNE-941 58
- LTV LTV-GICDM2-E300-F1
- LTV LTV-GICDM2-E400-V1
- LTV LTV-GICDM2-E400-V3
- Tiandy TC-NH6232ISA
- Tiandy TC-NH6244ISA-G
- VIVOTEK FD8379-HV
- VIVOTEK IB8377-H
- VIVOTEK IB8377-HT
- VIVOTEK IB8379

Thermal imaging cameras:

- Dahua DH-TPC-BF2120
- Hikvision DS-2TD2136-25
- Hikvision DS-2TD2615-7

DVR (HD-TVI):

- Hikvision DS-7208HUHI-F2/N

NVR:

- Glosav GLVR-32 IP
- Grundig GD-RN-AC2416N
- Grundig GD-RT-AT5016N
- RVi RVi-IPN64/8-4K-PRO-V.2



Video Capture Card:

- Yuan SC3C0N8

New features and improvements

- Dahua driver now supports GPS detector.
- ONVIF Generic and Bosch Generic drivers have been improved.
- Added support for additional features of 79 devices by the following vendors: Astrohn, Axis, Beward, Dahua, Everview, FineCCTV, Grundig, Hanwha Techwin, Hikvision, IDIS, LTV, Panasonic, Partizan, ROKA, RVi, STORM.

Documentation and installation

Operation of IP devices differs for various AxxonSoft products. Please refer [the table](#) to check what features and firmware versions of integrated IP devices are supported.

To download the installer for Drivers Pack 3.55, refer [here](#).

To install Drivers Pack, close the VMS, run the installation file IPDriverPack.msi, complete the installation, and restart the VMS.

If Drivers Pack 3.2.0 or an earlier version is installed, first go to "Windows Control Panel" → "Add/Remove Programs" and uninstall it.

Drivers Pack 3.55 is recommended to be used with **Axxon Intellect 4.10.4** and **Axxon Next 4.2.1**.