



Drivers Pack 3.60

Driver package of IP devices for Axxon Intellect and Axxon Next software

July 17, 2019. Release notes

For information about the Drivers Pack, refer [here](#).

126 new IP devices are integrated

IP cameras:

- Beward BV135P
- Beward B2710
- Beward B2710DR
- Beward B55-5H
- Beward B85-20H
- Beward B85-20H2
- Beward BC0271DR
- Beward BC134PTZ20P
- Beward BC85PTZ20H
- Beward BD134P
- Beward BD136P
- Beward BD90253Z30
- Beward BV136P
- Beward BV2204DR
- Beward NK55002D6
- Beward TZ134P
- Beward TZ135P
- Beward TZ136P
- Beward TZ2710DR
- Beward TZ85-20
- Beward BC0271DMR
- Beward BC0272DV
- Beward BC0272DVZ
- Beward BC0272RVQ
- Beward BC1640RCV2
- Beward TZ2720RZK
- Dahua DH-IPC-HFW5431E-ZE
- Dahua DH-ITC302-RF1A-IR
- D-Link DCS-4703E
- D-Link DCS-6517 HW A
- Hanwha Techwin XND-6080R
- Hanwha Techwin XND-6080RP
- Hanwha Techwin XNO-6080RP
- Hanwha Techwin XNV-6080R
- Hanwha Techwin XNV-6080RP
- Hikvision DS-2CD2435FWD-IS
- Hikvision DS-2CD1643G0-I
- Hikvision DS-2CD2083G0-I
- Hikvision DS-2CD2121G0-IS
- Hikvision DS-2CD2125G0-IMS
- Hikvision DS-2CD2145FWD-I
- Hikvision DS-2CD2145FWD-IS
- Hikvision DS-2CD2185G0-IMS
- Hikvision DS-2CD2345FWD-I
- Hikvision DS-2CD2435FWD-I
- Hikvision DS-2CD2435FWD-IW



- Hikvision DS-2CD2435FWD-IWS
- Hikvision DS-2CD2535FWD-I
- Hikvision DS-2CD2535FWD-IS
- Hikvision DS-2CD2535FWD-IWS
- Hikvision DS-2CD2545FWD-I
- Hikvision DS-2CD2623G1-IZ
- Hikvision DS-2CD2635FWD-IZS
- Hikvision DS-2CD2643G1-IZ
- Hikvision DS-2CD2643G1-IZS
- Hikvision DS-2CD2645G1-IZ
- Hikvision DS-2CD2645G1-IZS
- Hikvision DS-2CD2685G0-IZS
- Hikvision DS-2CD2723G1-IZ
- Hikvision DS-2CD2725G1-IZ
- Hikvision DS-2CD2735FWD-IZS
- Hikvision DS-2CD2743G1-IZ
- Hikvision DS-2CD2743G1-IZS
- Hikvision DS-2CD2745G1-IZ
- Hikvision DS-2CD2745G1-IZS
- Hikvision DS-2CD2783G0-IZS
- Hikvision DS-2CD2785G0-IZS
- Hikvision DS-2CD2785G1-IZ
- Hikvision DS-2CD2785G1-IZS
- Hikvision DS-2CD2935FWD-I
- Hikvision DS-2CD2935FWD-IS
- Hikvision DS-2CD2H35FWD-IZS
- Hikvision DS-2CD2H45FWD-IZS
- Hikvision DS-2CD2H83G0-IZS
- Hikvision DS-2CD2T27G1-L
- Hikvision DS-2CD2T45FWD-I5
- Hikvision DS-2CD2T45FWD-I8
- Hikvision DS-2CD2T46G1-4I
- Hikvision DS-2CD2T83G0-I5
- Hikvision DS-2CD2T83G0-I8
- Hikvision DS-2CD2T85G1-I5
- Hikvision DS-2CD2T85G1-I8
- Hikvision DS-2DE5225IW-AE
- Hikvision DS-2DF5225X-AE3
- Hikvision DS-2DF5225X-AEL
- Hikvision DS-2DF5232X-AE3
- Hikvision DS-2DF5232X-AEL
- Hikvision DS-2DF6225X-AEL
- Hikvision DS-2DF6236X-AEL
- Hikvision DS-2DF7225IX-AEL
- Hikvision DS-2DF7225IX-AELW
- Hikvision DS-2DF7232IX-AEL
- Hikvision DS-2DF7232IX-AELW
- Hikvision DS-2DF8225IX-AEL
- Hikvision DS-2DF8225IX-AELW
- Hikvision DS-2DF8236I5X-AELW
- Hikvision DS-2DF8425IX-AEL
- Hikvision DS-2DF8425IX-AELW
- Hikvision DS-2DF8436I5X-AELW
- Hikvision S-2CD2535FWD-IW
- IndigoVision 11000E
- LTV CNE-623 48
- LTV CNE-723 48
- LTV CNE-923 48
- Milesight MS-C2983-PB
- Milesight MS-C5383-PB
- MOBOTIX T25
- Panasonic WV-X8570N



- SMAVID SMA-IPB-700222
- SMAVID SMA-IPB-700224
- SMAVID SMA-IPD-700223
- SMAVID SMA-IPD-700225

NVR:

- Dahua DH-NVR4116-16P-4KS2
- Dahua DH-NVR4204-P-4KS2
- Dahua DH-NVR4216-16P-4KS2
- Dahua DH-NVR4216-4KS2
- Dahua DH-NVR4232-16P-4KS2
- Dahua DH-NVR4232-4KS2
- Dahua DH-NVR4416-16P-4KS2
- Dahua DH-NVR4432-16P-4KS2
- Dahua DH-NVR4432-4KS2
- Dahua DH-NVR4832-16P-4KS2
- Dahua DH-NVR4832-4KS2

I/O Module:

- MOXA ioLogik E2210

DVR (HD-CVI):

- RVi RVi-HDR08MA

Intercom:

- Beward DC11EP

New features and improvements

- New MOXA driver has been integrated;
- Added support for additional features of 158 devices by the following vendors: ABUS, Axis, Beward, Dahua, D-Link, GIT, Grundig, Hikvision, LTV, Panasonic, RVi, SMAVID, Sony, STORM, Tibbo, VIVOTEK.



Documentation and installation

Operation of IP devices differs for various AxxonSoft products. Please refer to [the table](#) to check what features and firmware versions of integrated IP devices are supported.

To download the installer for Drivers Pack 3.60, refer [here](#).

To install Drivers Pack, close the VMS, run the installation file IPDriverPack.msi, complete the installation, and restart the VMS.

If Drivers Pack 3.2.0 or an earlier version is installed, first go to "Windows Control Panel" → "Add/Remove Programs" and uninstall it.

Drivers Pack 3.60 is recommended to be used with **Axxon Intellect 4.10.4** and **Axxon Next 4.3.2**.