



## Drivers Pack 3.62

### Driver package of IP devices for Axxon Intellect and Axxon Next software

#### October 07, 2019. Release notes

For information about the Drivers Pack, refer [here](#).

### 109 new IP devices are integrated

#### IP cameras:

- Beward BD4685
- Beward BD4685DRZ
- Beward BD4685DVZ
- Beward SV3210DVZ
- Dahua DH-IPC-HDBW8241E-Z
- Dahua DH-IPC-HFW5541T-ASE
- Dahua DH-IPC-HFW8241E-Z
- Dahua DH-ITC214-PH2A
- Dahua DH-ITC237-PU1B-IR
- Dahua DH-NVR4116-8P-4KS2
- Hikvision DS-2CD1023G0-I
- Hikvision DS-2CD1043G0-I
- Hikvision DS-2CD1123G0-I
- Hikvision DS-2CD1143G0-I
- Hikvision DS-2CD1323G0-I
- Hikvision DS-2CD1743G0-I
- Hikvision DS-2CD2126G1-I
- Hikvision DS-2CD2126G1-IS
- Hikvision DS-2CD2146G1-I
- Hikvision DS-2CD2146G1-IS
- Hikvision DS-2CD2326G1-I
- Hikvision DS-2CD2346G1-I/SL
- Hikvision DS-2CD2425FWD-I
- Hikvision DS-2CD2455FWD-I
- Hikvision DS-2CD2626G1-IZ
- Hikvision DS-2CD2626G1-IZS
- Hikvision DS-2CD2646G1-IZ
- Hikvision DS-2CD2646G1-IZS
- Hikvision DS-2CD2721G0-IS
- Hikvision DS-2CD2726G1-IZ
- Hikvision DS-2CD2726G1-IZS
- Hikvision DS-2CD2745FWD-IZS
- Hikvision DS-2CD2746G1-IZS
- Hikvision DS-2CD2T26G1-2I
- Hikvision DS-2CD2T26G1-4I
- Hikvision DS-2CD2T26G1-4I/SL
- Hikvision DS-2CD2T46G1-2I
- Hikvision DS-2CD2T46G1-4I
- Hikvision DS-2CD2T46G1-4I/SL
- Hikvision DS-2CD3023G0-I
- Hikvision DS-2CD3025G0-I
- Hikvision DS-2CD3123G0-I
- Hikvision DS-2CD3123G0-IS
- Hikvision DS-2CD3125G0-I
- Hikvision DS-2CD3323G0-I
- Hikvision DS-2CD3325G0-I



- Hikvision DS-2CD3523G0-IS
- Hikvision DS-2CD3525G0-IS
- Hikvision DS-2CD3542FWCD-ITD
- Hikvision DS-2CD3623G0-IZS
- Hikvision DS-2CD3625G0-IZS
- Hikvision DS-2CD3723G0-IZS
- Hikvision DS-2CD3725G0-IZS
- Hikvision DS-2CD3H23G0-IZS
- Hikvision DS-2CD3H25G0-IZS
- Hikvision DS-2CD3T23G0-I5
- Hikvision DS-2CD3T23G0-I8
- Hikvision DS-2CD3T25G0-I
- Hikvision DS-2CD4026FWD-IZ/P
- Hikvision DS-2CD4A26FWD-LZSWG/P
- Hikvision DS-2CD7026G0/EP-IH
- Hikvision DS-2CD7A26G0/P-IZHS
- Hikvision DS-2CD7A26G0/P-LZHS
- Hikvision DS-2CD7A26G0/P-LZS
- Hikvision DS-2DE5432IW-AE
- Hikvision DS-2DE7232IW-AE
- Hikvision DS-2DF8836I5X-AELW
- Homeland Safety Systems HSS-T9302-IP-32G
- Homeland Safety Systems HSS-T9302-IP-AUD
- Homeland Safety Systems HSS-T9302-IP-AW
- LTV LTV-GICDM3-E200-LM3
- LTV LTV-GICDM3-E200-M3
- Novicam NC21WP
- Panasonic BB-HCM381A
- VIVOTEK FD9165-HT
- VIVOTEK FD9365-EHTV
- VIVOTEK FD9365-HTV
- VIVOTEK FD9365-HTVL
- VIVOTEK IB9365-EHT
- VIVOTEK IB9365-HT
- VIVOTEK IB9391-EHT
- VIVOTEK IP9165-HP
- VIVOTEK IP9165-HT
- VIVOTEK IP9165-LPC

### Fisheye Cameras:

- Hikvision DS-2CD6365G0E/RC
- Hikvision DS-2CD6365G0E-I
- Hikvision DS-2CD6365G0E-IS
- Hikvision DS-2CD6365G0E-IV
- Hikvision DS-2CD6365G0E-IVS
- Hikvision DS-2CD6365G0E-S/RC
- Hikvision DS-2CD6365G0-I
- Hikvision DS-2CD6365G0-IS
- Hikvision DS-2CD6365G0-IV
- Hikvision DS-2CD6365G0-IVS
- Hikvision DS-2CD63C5G0E/RC
- Hikvision DS-2CD63C5G0E-I
- Hikvision DS-2CD63C5G0E-IS
- Hikvision DS-2CD63C5G0E-IV
- Hikvision DS-2CD63C5G0E-IVS
- Hikvision DS-2CD63C5G0E-S/RC



- Hikvision DS-2CD63C5G0-I
- Hikvision DS-2CD63C5G0-IS
- Hikvision DS-2CD63C5G0-IV

### NVR:

- ABUS NVR10010
- ABUS NVR10030

### HDVR:

- Hikvision DS-7208HUHI-K1
- Hikvision DS-7208HUHI-K2/P
- Hikvision DS-7216HUHI-K2/P
- ST ST-HDVR-8 L PRO

## New features and improvements

- FFmpeg, Virtual и Panasonic Stub drivers have been improved;
- Added support for additional features of 58 devices by the following vendors: ACTi, Astrohn, Axis, Beward, Bosch, Dahua, GIT, Grundig, Hikvision, Huawei, Jassun, KONEKT, LTV, MAGO, MOBOTIX, Panasonic, Tibbo, VIVOTEK.

## Documentation and installation

Operation of IP devices differs for various AxxonSoft products. Please refer to [the table](#) to check what features and firmware versions of integrated IP devices are supported.

To download the installer for Drivers Pack 3.62, refer [here](#).

To install Drivers Pack, close the VMS, run the installation file IPDriverPack.msi, complete the installation, and restart the VMS.

If Drivers Pack 3.2.0 or an earlier version is installed, first go to "Windows Control Panel" → "Add/Remove Programs" and uninstall it.

**Drivers Pack 3.62** is recommended to be used with **Axxon Intellect 4.10.4** and **Axxon Next 4.3.2**.