



Drivers Pack 3.63

Driver package of IP devices for Axxon Intellect and Axxon Next software

December 04, 2019. Release notes

For information about the Drivers Pack, refer [here](#).

115 new IP devices are integrated

IP cameras:

- Amatek AC-IDV203ZA
- Axis M3058
- Axis P1375
- Axis P1375-E
- Axis Q6125-LE
- Bosch FLEXIDOME IP corner 9000 MP
- ComOnyx CO-LD2225P
- Dahua DH-IPC-HF5431E-E
- Dahua DH-IPC-PSDW81642M-E9-H-A360
- Dahua DH-IPC-PSDW81649M-A360-D440
- GIGA GS0148
- Grundig GD-CI-AP2605B
- Grundig GD-CI-AP2627T
- Grundig GD-CI-AP2627V
- Grundig GD-CI-AP4617C
- Grundig GD-CI-AP4617W
- Grundig GD-CI-AT2637TH
- Grundig GD-CI-AT3637T
- Grundig GD-CI-AT4637TH
- Grundig GD-CI-AT4637VH
- Hikvision DS-2CD1723G0-I
- Hikvision DS-2CD2010F-I
- Hikvision DS-2CD2010F-IW
- Hikvision DS-2CD2010-I
- Hikvision DS-2CD2020-I
- Hikvision DS-2CD2327G3E-L
- Hikvision DS-2CD2721G0-I
- Hikvision DS-2CD2D21G0/M-D/NF
- Hikvision DS-2CD2E10F
- Hikvision DS-2CD2E20F
- Hikvision DS-2CD2E20F-W
- Hikvision DS-2CD2T10-I3
- Hikvision DS-2CD2T10-I5
- Hikvision DS-2CD2T10-I8
- Hikvision DS-2CD2T20-I3
- Hikvision DS-2CD2T20-I5
- Hikvision DS-2CD2T20-I8
- Hikvision DS-2CD2T21G0-I
- Hikvision DS-2CD2T27G3E-L
- Hikvision DS-2CD4135F-IZ
- Hikvision DS-2CD4324FWD-I
- Hikvision DS-2CD4324FWD-IH
- Hikvision DS-2CD4324FWD-IHS
- Hikvision DS-2CD4324FWD-IS
- Hikvision DS-2CD4324FWD-IZ



- Hikvision DS-2CD4324FWD-IZH
- Hikvision DS-2CD4324FWD-IZHS
- Hikvision DS-2CD4324FWD-IZS
- Hikvision DS-2CD4524FWD-I
- Hikvision DS-2CD4524FWD-IH
- Hikvision DS-2CD4524FWD-IM
- Hikvision DS-2CD4524FWD-IZ
- Hikvision DS-2CD4524FWD-IZH
- Hikvision DS-2CD4524FWD-IZHM
- Hikvision DS-2CD4524FWD-IZM
- Hikvision DS-2CD4635F-IZ
- Hikvision DS-2CD4635F-IZH
- Hikvision DS-2CD4635F-IZHS
- Hikvision DS-2CD4635F-IZS
- Hikvision DS-2CD4A26FWD-IZS/PWG
- Hikvision DS-2CD4A26FWD-IZSWG/P
- Hikvision DS-2CD4A35F-IZ
- Hikvision DS-2CD4A35F-IZH
- Hikvision DS-2CD4A35F-IZHS
- Hikvision DS-2CD4A35F-IZS
- Hikvision DS-2CD5026G0/E-HI
- Hikvision DS-2CD5028G0/E-HI
- Hikvision DS-2CD5A85G0-IZHS
- Hikvision DS-2DE7223IW-AE
- Hikvision DS-2DE7225IW-AE
- Hikvision DS-2DE7230IW-AE
- Hikvision DS-2PT3122IZ-DE3
- Hikvision DS-2PT3326IZ-DE3
- Hikvision DS-2PT5326IZ-DE
- LTV CNE-421 00
- LTV LTV-GHU-320H-12-220-LTV-GICDM2-E401-V1
- LTV LTV-GHU-320H-12-220-LTV-GICDM2-E401-V2
- MOBOTIX M16B
- Sentryway IP SmartTrack
- Sony SNC-VB770
- Uniview IPC2322EBR5-HDUPZ
- Uniview IPC3232ER3-DUVZ
- VIVOTEK FD9389-HV

Thermal imaging cameras:

- Hikvision DS-2TD2136-10/V1
- Hikvision DS-2TD2136-15/V1
- Hikvision DS-2TD2136-25/V1
- Hikvision DS-2TD2136-35/V1
- Hikvision DS-2TD2136-7/V1
- Hikvision DS-2TD2137-10/V1
- Hikvision DS-2TD2137-15/V1
- Hikvision DS-2TD2137-25/V1
- Hikvision DS-2TD2137-35/V1
- Hikvision DS-2TD2137-7/V1
- Hikvision DS-2TD2617-3/V1
- Hikvision DS-2TD2617-6/V1
- Hikvision DS-2TD2836-25
- Hikvision DS-2TD2836-25/V1
- Hikvision DS-2TD2836-50
- Hikvision DS-2TD2836-50/V1



- Hikvision DS-2TD2866-25
- Hikvision DS-2TD2866-25/V1
- Hikvision DS-2TD2866-50
- Hikvision DS-2TD2866-50/V1

Fisheye cameras:

- LTV CNE-740 K0

DVR:

- IDIS ID3916H
- IDIS ID3932H
- Vitek VT-TNR3216P-F

HDVR:

- Dahua DH-XVR4104C-S2
- Dahua DH-XVR4208A-S2
- Hikvision DS-7204HUHI-K1
- Hikvision DS-7208HQHI-K2
- Hikvision DS-7216HQHI-K2
- HiWatch DS-H204U(B)

Intercoms:

- Beward DKS15102
- Beward DKS850120

New features and improvements

- Operator actions recording capabilities has been added for Intellect software.
- Added support for additional features of 106 devices by the following vendors: Beward, Dahua, GIT, Grundig, Hanwha Techwin, Hikvision, Homeland Safety Systems, LTV, Milesight, Panasonic, SMAVID, Tibbo, VIVOTEK.

Documentation and installation

Operation of IP devices differs for various AxxonSoft products. Please refer to [the table](#) to check what features and firmware versions of integrated IP devices are supported.

To download the installer for Drivers Pack 3.63, refer [here](#).

To install Drivers Pack, close the VMS, run the installation file IPDriverPack.msi, complete the installation, and restart the VMS.

If Drivers Pack 3.2.0 or an earlier version is installed, first go to "Windows Control Panel" → "Add/Remove Programs" and uninstall it.

Drivers Pack 3.63 is recommended to be used with **Axxon Intellect 4.10.4** and **Axxon Next 4.3.2**.